

LIMITED WARRANTY

ADESSO provides one year limited warranty for the quality of all its products in materials and workmanship.

During this period, ADESSO will repair or replace all merchandise, which proved to be defective. However, ADESSO will not warranty any product which has been subjected to improper freight Handling, shipping abuse, neglect or unauthorized repair or installation. The warranty also will not cover products installed with Non-ADESSO components and product with broken sealed and assembly trace. After replacement of RMA, ADESSO reserves the right to request the total cost of the replacement products with broken seals or assembly trace.

If you discover a defect, Adesso will, at its option, repair or replace the product at no charge to you, provided you return it during the warranty period with transportation charges pre-paid to Adesso. You must contact Adesso at support@adesso.com for a Return Merchandise Authorization number (RMA) prior to returning any product. For each product returned for warranty service, please include your name, shipping address (no P.O. Box), telephone number, copy of the bill of sale as proof of purchase and have the package clearly marked with your RMA number.

SUPPORT

Website Support:

We have listed most of our FAQ's (Frequently Asked Questions) at:

<http://www.adesso.com/faqs.asp>.

Please visit our FAQ Service & Support pages before you contact our E-mail or Telephone Support.

Email Support:

If our FAQ's do not help you resolve your issues, please email support@adesso.com

Telephone Support:

Toll Free: (800) 467-1195
9:00AM to 6:00PM PST Monday - Friday.



Adesso Inc.

160 Commerce Way
Walnut, CA 91789
Phone (909) 839-2929
Fax (909) 839-2930
www.adesso.com



USER'S GUIDE



Wireless Mini Trackball
Keyboard

MODEL: WKB-3000UB

INTRODUCTION

Enjoy the freedom of wireless connectivity with Adesso's wireless mini Keyboard with Optical trackball. The keyboard and trackball allow you to work up to 100 feet away from the USB receiver connected to your computer. In addition, the optical trackball provides great accuracy with minimal hand movement due to its 800 dpi resolution. The lightweight and stylish keyboard offers mobility and comfort wherever you type. Take complete control of your desktop with hotkeys. The different hotkeys give you quick access to some of your most common tasks such as e-mail access, volume control, and launching your web browser - at the push of a button.

FEATURES


- Streamlined full-featured RF keyboard built-in Track Ball, with Optical Technology
- 2.4 GHz radio frequency, 100 feet effective working range, USB port
- 360-degree navigation, sleek and elegant design.
- With notebook keyboard module enables handheld operation and effortless typing.

PACKAGE CONTENTS

- One (1) WKB-3000UB Keyboard
- One (1) User's Guide


INSTALLATION

1. Open the battery cover under the keyboard and place 4 AA batteries inside the battery compartment. Close the battery compartment cover.
2. Plug the RF Receiver of the keyboard into the USB ports of your computer.
3. Turn on your computer
4. Setting ID:
 - a. Press ID button on Dongle receiver. (Picture A), the Green LED will flash which means the ID is searching.




Picture A

- b. Press the ID button on the keyboard. (Picture B), After you please the ID button on the keyboard, the green LED light will turn off on the dongle receiver which means the connection was successful.



Picture B

HOTKEYS DESCRIPTION



Notice:

- RF Signal LED on the receiver will flash when the keyboard is being used.
- When Battery Low LED lights, it means the keyboard requires a change of batteries.

TROUBLESHOOTING

If you cannot get your keyboard to work after installation, please try the following:

1. Make sure you have connected the receiver correctly to the computer. The receiver has been properly plugged onto computer's USB ports.
2. Make sure you have inserted four AA batteries into its compartment correctly.
3. Move the keyboard closer to the receiver.
4. If using more than two units and interfere occurred, please reset ID again.